



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 5  
77 WEST JACKSON BOULEVARD  
CHICAGO, ILLINOIS 60604**

**DEC 09 2019**

**DATE:**

**SUBJECT:** CLEAN AIR ACT INSPECTION REPORT  
Krystal Transport, Dearborn, Michigan

**FROM:** Cody Yarbrough, Environmental Engineer  
AECAB (MN/OH)

**THRU:** Brian Dickens, Section Chief  
AECAB (MN/OH)

**TO:** File

---

**BASIC INFORMATION**

**Facility Name:** Krystal Transport

**Facility Location:** 5000 Wyoming Ave. Suite 152 Dearborn, MI 48126

**Date of Inspection:** October 29, 2019

**EPA Inspector(s):**

1. Cody Yarbrough, Environmental Engineer

**Other Attendees**

1. Robin, Dispatcher, Krystal Transport

**Contact Email Address:** No email provided

**Purpose of Inspection:** Emission control device tampering on vehicles and engines.

**Facility Type:** Heavy duty diesel trucking fleet.

**Regulations Central to Inspection:** Emission control device tampering prohibitions. CAA Section 203(a)(3)(a)-(b).

**Arrival Time:** 2:10 PM CDT

**Departure Time:** 2:30 PM CDT

**Inspection Type:**

- ☒ Unannounced Inspection  
☐ Announced Inspection

**OPENING CONFERENCE**

- ☒ Credentials Presented  
☒ CBI warning to facility provided

The following information was obtained verbally from Robin unless otherwise noted.

**Process Description:**

Krystal Transport operates a fleet of approximately 24 heavy duty diesel engine trucks. Most trucks are newer (~2019) Kenworths.

**Staff Interview:** Robin stated that the Wyoming Avenue address is only an office space and Krystal Transport's trucks are stored elsewhere. She was unsure of the location where the trucks are stored but provided 14250 Mark Twaine St. Detroit, Michigan 48227 as a potential location. She said the primary contact for the business is Klaus Koteci (313-312-7590) who was unavailable during the inspection. Robin left a message with Mr. Koteci requesting that he call Mr. Yarbrough to set up a time to inspect Krystal Transport's fleet.

**TOUR INFORMATION**

**EPA toured the facility:** No

**Data Collected and Observations:**

After leaving the facility, Mr. Yarbrough drove to the address provided by Robin. This address contained a residence with no heavy-duty diesel trucks nearby.

**Photos and/or Videos:** were not taken during the inspection.

**Field Measurements:** were not taken during this inspection.

**SIGNATURES**

Report Author: Cody Yarbrough Date: 12-5-19  
Section Chief: Brian D. Dutton Date: 12/9/19